ALDER FIELD SERVICES

Maintenance handover

Cedar Court | MT-017

Summary

13 November 2026

Filter replaced and airflow checked. No faults found during the handover.

Checks completed

1. Replace the return-air filter.
2. Check the airflow at the intake.
3. Record the result in the service log.

Follow-up

Inspect the intake grille at the next scheduled visit.

Leave on site

- Copy of the maintenance handover
- Filter packaging for the site team